

POOL SAFETY BARRIER INSPECTION & CERTIFICATION



0458 287 108

We offer professional Pool Safety Barrier Inspection & Certification services supported by formal national SPASA Australian Training & Accreditation (SPASA Accredited PSIREG001—Pool Safety Inspection) backed up with SA Builders Licence.









We provide:

- comprehensive report on findings
- qualified trades to action improvements
- formal certification
- and more!

Contact us

- ♠ Adelaide and SA wide
- **U** 0458 287 108
- john@psbi.com.au
- psbi.com.au





Our formal training and industry experience provides our certification personnel with the skills and knowledge to professionally and accurately inspect and certify your pool safety barrier.



Issues such as gates not self-closing/self-latching can be caused by deteriorated hinges and latches; or by obstructions such as over grown shrubs. These areas are quickly identified and solutions provided.



Upon inspection of your pool safety barrier and confirmation that it conforms to Australian Standards a formal letter of certification will be issued.



We currently work with many Real Estate Agents in preparation for house sales, ensuring Pool Barriers meet current legislation and are certified.